

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / TECH/ WF.48-Oct-2022 /140 / 2022-23.

Dated:25/02/2023

Name of the Work: Construction and protection of retaining wall (right hand side) for nallah from Maruti temple to hill side (Om Divine) building at Mangor Hill Baina in Vasco Constituency.

Sample Sent by: Assistant Engineer, SD II, WD II, WRD, GOGAL -Goa

Letter No: No. WRD/SD II/WD II/F-03/232/2022-23.

Dated:- 08-02-2023.

Received on: 09-02-2023.

Date of Testing: 10/2/2023

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.48/01/2022	Coarse Sand	FM Silt & Clay Grading	2.394 1.80% Zone III	2.3 to 3.1 Upto 5% Zone I to III	
F.48/02/2022	Aggregate-20 mm	Grading		As per IS-383:2016	To get the20mm graded aggregate nominal size blend
F.48/03/2022	Aggregate- 10 mm	Grading		As per IS-383:2016	20mm & 10 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD II, WD II, WRD, GOGAL -Goa
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfong- Goa.
- 3) The Surveyor of Works, Quality Control, C.P.O., Water Resources Dept., Sinchai Bhavan, Alto Porvorim-Goa.
- 4) Office File