GOVERNMENT OF GOA OFFICE OF THE ASSISTANT ENGINEER SUB DIVISION III (SOUTH), QUALITY CONTROL LABORATORY, WATER RESOURCES DEPARTMENT, GOGAL, MARGAO- GOA.

PLEASE FIND THE TEST RESULTS OF CEMENT AS DETAILED BELOW:

Name of work:- Improvement and Strengthening of existing retaining wall & Weir at Sarzora Lake in Salcete Taluka (2nd Call).

Type of Cement: Ordinary Portland cement Brand / Grade: JSW/43 grade

Source of receipt: Assistant Engineer, SD V, WD XII, WRD, Quepem- Goa.

Ref. Letter No: WRD/ SD V/WD XII/F.70/26/2024-25. **Dated:** 15-05-2024.

Qty. Represented:

L.S. No: F. 175/5/2023.

Physical Properties

Sr.	Description	Test results	Requirements as per I.S.
No			
1	Fineness. (% retained on 9		Not more than 10%
	micron sieve)	3 %	
2	Setting Time in (Minutes)		
	xix) Initial	186 minutes	Not less than 30 Min
	xx) Final.	294 minutes	Not more than 600 Min.
3	Minimum Com Strength Kg/Cm ²		
	i) 72 hrs. ± 1 hrs.	363.33 Kg/cm2	Not less than 230.0Kg/cm2
	ii) 168 hrs. ±2hrs	463.33 Kg/cm2	Not less than 330.0Kg/cm2
	iii) 672 hrs. ±4 hrs	566.66 Kg/cm2	Not less than 430.0Kg/cm2
4	Consistency of cement.	28 %	

To,

The Asst. Engineer.SD V, WD XII, WRD, Quepem-Goa.

C.W.C. Submitted to:

2. The Exe. Eng. W.D. XI, WRD, Rawanfond–Goa.

3. S.W.II, CPO, WRD, Sinchai Bhavan , Alto, Porvorim – Goa.

4. Office file.