GOVERNMENT OF GOA WATER RESOURCES DEPARTMENT S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY

Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59/ W.F. 148/2021 /**18** / 2022-23 dated:

dated: 28-10-2022

Name of the Work: Stabilization on the left bank of river Zuari in No.42/7 at Baag Shirfod in Curchorem Constituency.

Sample Sent by :- Assistant Engineer, SD V, WD XII, WRD, Quepem-Goa.

Letter no:- No. WRD/WD XII/SD V/ F.15/116/2022-23.

Dated:- 26-08-2022.

Received On:

27-08-2022

Date of Tesing: 30-08-2022

REPORT	

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
		FM	2.702	2.3 to 3.1	
F.148/01/2021 Coarse Sand	Coarse Sand	Silt & Clay	1.60%	Upto 5%	
	Grading	Zone II	l to III Zone		
		FM	2.380	2.3 to 3.1	
F.148/02/2021	Fine Sand	Silt & Clay	4.80%	Upto 5%	
		Grading	Zone III	l to III Zone	
F.148/03/2021	Aggregate-20 mm	Grading		As per IS-383-1970	To get the20mm graded
		_		(Re-affirmed in 1990)	aggregate nominal size blend
F.148/04/2021	Aggregate- 10 mm	Grading		As per IS-383-1970	20mm & 10 mm metal
				(Re-affirmed in 1990)	in 1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to 1) Assistant Engineer, SDV, WD XII, WRD, Quepem, Goa.

2) The Executive Engineer, Works Division XII, WRD, Quepem, Goa.

3) Executive Engineer, WD XI, WRD, Rawanfond -Goa.

4) Office File.