

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / TECH / WF. 206-Oct-2024 /2025-26/ 189

Dated: 16/06/2025

Name of the Work: Reconstruction of platform near Ganesh Visarjan site, next to Saiba restaurant at Cunchelim, Mapusa ward
1 of Mapusa Constituency.

Sample Sent by: Assistant Engineer , SD II , WD I , WRD , Mapusa - Bardez - Goa.

Letter No: No.WRD/ WD I/ SD II/F.24/2025-26/157

Dated:- 12/6/2025

Received on: 13-06-2025

Date of Testing 16-06-2025

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F. 206/01/2024	Coarse Sand	FM Silt & Clay Grading	2.589 1.90% Zone III	2.3 to 3.1 Upto 5% I to III Zone
F. 206/02/2024	Aggregate-20 mm	Grading	As per IS-383:2016	To get the 20mm graded aggregate nominal size blend
F. 206/03/2024	Aggregate- 12.5 mm	Grading	As per IS-383:2016	20mm & 12.5 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

- Copy submitted to
- 1) Assistant Engineer, SD II, WD I, WRD, Mapusa- Bardez - Goa
 - 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
 - 3) The Executive Engineer, Works Division I, WRD, Porvorim- Goa.
 - 4) The Surveyor of Works, Quality Control, C.P.O., Water Resources Dept., Sinchai Bhavan, Alto Porvorim-Goa.
 - 5) Office File.