

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / TECH/ W.F. 22-Oct-2024/2024-25/192

dated:18/11/24

Name of the Work: Improvement to existing nallah near Manovikas School at Gogol in Fatorda Assembly Constituency.

Sample Sent by: Assistant Engineer, SD III, WD III, WRD, Gogol- Margao -Goa

Letter No: No. 353/SDIII/ WD III/WRD/24-25/288.

Dated:- 14-11-2024

Received on: 14-11-2024

Date of Testing 16-11-2024

REPORT

Sr No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F. 22/01/2024	Coarse Sand	FM Silt & Clay Grading	2.410 1.30% Zone III	2.3 to 3.1 Upto 5% I to III Zone
F. 22/02/2024	Metal Sand	FM Silt & Clay Grading	2.970 2.30% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
F. 22/03/2024	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
F. 22/04/2024	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	

Junior Engineer

Assistant Engineer

- Copy submitted to
- 1) Assistant Engineer, SD III, WD III, WRD, Gogol- Margao-Goa.
 - 2) Executive Engineer, WD XI, WRD, Rawanfond-Goa.
 - 3) Executive Engineer, WD III, WRD, Ponda -Goa.
 - 4) The Surveyor of Works, Quality Control, C.P.O., Water Resources Dept., Sinchai Bhavan, Alto Porvorim-Goa.
 - 5) Office File.