

**GOVERNMENT OF GOA**  
**WATER RESOURCES DEPARTMENT**  
**S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY**  
**Gogol - Margao - Goa.**

No. WRD / WD XI / SDIII / TECH / WF. 15 -Oct-2023 /2023-24/248

Dated:25/11/23

Name of the Work: Improvement to nallah bank near the house of Bal Sahakari in V.P. Curti- Khandepar in Ponda Taluka.

Sample Sent by: Assistant Engineer , SD IV , WD XI , WRD , Ponda - Goa.

Letter No: WRD/ WD XI/SD IV/F.CF/459/2023-24.

Dated:- 21-11-2023

Received on: 21-11-2023

Date of Testing 23-11-2023

**REPORT**

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.15/01/2023	Coarse Sand	FM Silt & Clay Grading	2.664 2.80% Zone III	2.3 to 3.1 Upto 5% I to III Zone	
F.15/02/2023	Metal Sand	FM Silt & Clay Grading	2.988 2.00% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
F.15/03/2023	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend
F.15/04/2023	Aggregate- 12.5 mm	Grading		As per IS-383:2016	20mm & 12.5 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD IV, WD XI, WRD, Ponda- Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) The Surveyor of Works, Quality Control, C.P.O., Water Resources Dept., Sinchai Bhavan, Alto Porvorim-Goa.
- 4) Office File.