

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / TECH/WF. 29-Oct-2023 /2023-24/261

dated:7/12/23

Name of the Work: Maintenance and repairs to the S.I.P main canal from Ch.15.00 to 17.05 kms in Quepem Taluka for the year 2023-24.

Sample Sent by: Assistant Engineer, SD IV, WD XIV, WRD, Quepem -Goa

Letter No: No.WRD/ SD IV/WD XIV/F.18/85/2023-24.

Dated:- 05-12-2023.

Received on: 5/12/2023

Date of Testing 7/12/2023

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.29/01/2023	Coarse Sand	FM Silt & Clay Grading	2.418 2.00% Zone III	2.3 to 3.1 Upto 5% I to III Zone	
F.29/02/202	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the20mm graded aggregate nominal size blend
F.29/03/2023	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	20mm & 10 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

- Copy submitted to
- 1) Assistant Engineer, SD IV, WD XIV, WRD, Quepem- Goa.
 - 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
 - 3) The Executive Engineer, Works Division XIV, WRD, Rawanfond- Goa.
 - 4) The Surveyor of Works,Quality Control, C.P.O.,Water Resources Dept., Sinchai Bhavan,Alto Porvorim-Goa.
 - 5) Office File.