

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / TECH / WF. 93-Oct-2024 /2024-25/348

Dated: 18/02/2025

Name of the Work: Construction of protection wall behind Mystical Rose Appartment in Sy.No. 19/5 in V.P. Davorlim Dicarvale in Velim Constituency of Salcete Taluka.

Sample Sent by: Assistant Engineer , SD III , WD II , WRD , Fatorda - Goa.

Letter No: No.WRD.SD III/WD II/F.77/277/2024-25.

Dated:- 12/2/2025

Received on: 14-02-2025

Date of Testing 17-02-2025

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F. 93/01/2024	Coarse Sand	FM Silt & Clay Grading	2.518 3.60% Zone III	2.3 to 3.1 Upto 5% I to III Zone
F. 93/02/2024	Aggregate-20 mm	Grading	As per IS-383:2016	To get the 20mm graded aggregate nominal size blend
F. 93/03/2024	Aggregate- 10 mm	Grading	As per IS-383:2016	20mm & 10 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

- Copy submitted to
- 1) Assistant Engineer, SD III, WD II, WRD, Fatorda - Goa
 - 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
 - 3) The Executive Engineer, Works Division II, WRD, Rawanfond- Goa.
 - 4) The Surveyor of Works,Quality Control, C.P.O.,Water Resources Dept., Sinchai Bhavan,Alto Porvorim-Goa.
 - 5) Office File.