

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / TECH / WF. 86-Oct-2023 /2023-24/400

Dated:08/3/24

Name of the Work: Construction of Access on nallah passing along Assolna to Betul road in Village Assolna in Salcete Taluka.

Sample Sent by: Assistant Engineer , SD I , WD II , WRD , Rawanfnd- Goa.

Letter No: WRD/SD I/ WD II/ F.Esst/730/2023-24.

Dated:- 19-02-2024

Received on: 1/3/2024

Date of Testing 4/3/2024

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.86/01/2023	Coarse Sand	FM Silt & Clay Grading	2.586 1.30% Zone III	2.3 to 3.1 Upto 5% I to III Zone
F.86/02/2023	Aggregate-20 mm	Grading	As per IS-383:2016	To get the 20mm graded aggregate nominal size blend
F.86/03/2023	Aggregate- 10 mm	Grading	As per IS-383:2016	20mm & 10 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

- Copy submitted to
- 1) Assistant Engineer, SD I, WD II, WRD, Rawanfnd- Goa
 - 2) The Executive Engineer, Works Division XI, WRD, Rawanfnd- Goa.
 - 3) The Executive Engineer, Works Division II, WRD, Rawanfnd- Goa.
 - 4) The Surveyor of Works,Quality Control, C.P.O.,Water Resources Dept., Sinchai Bhavan,Alto Porvorim-Goa.
 - 5) Office File.