

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / TECH / WF. 149-Oct-2023 /2023-24/401

Dated: 23/03/24

Name of the Work: Improvement of nallah bank LHS side at Portem in Sy.No. 45 plot No- A-148 V.P. Vaddem Curdi in Sanguem Taluka.

Sample Sent by: Assistant Engineer , SD I , WD XII , WRD , Pajimol- Sanguem- Goa.

Letter No: WRD/ SD I/ WD XII/ F.47/481/2023-24.

Dated:- 22-03-2024

Received on: 22-03-2024

Date of Testing 22-03-2024

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F. 149/01/2023	Coarse Sand	FM Silt & Clay Grading	2.819 2.60% Zone III	2.3 to 3.1 Upto 5% I to III Zone
F. 149/02/2023	Metal Sand	FM Silt & Clay Grading	3.089 3.40% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
F. 149/03/2023	Aggregate-20 mm	Grading	As per IS-383:2016	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
F. 149/04/2023	Aggregate- 10 mm	Grading	As per IS-383:2016	

Junior Engineer

Assistant Engineer

- Copy submitted to
- 1) Assistant Engineer, SD I, WD XII, WRD, Pajimol- Sanguem- Goa.
 - 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
 - 3) The Executive Engineer, Works Division XII, WRD, Gogol- Margao- Goa.
 - 4) The Surveyor of Works, Quality Control, C.P.O., Water Resources Dept., Sinchai Bhavan, Alto Porvorim-Goa.
 - 5) Office File.