

**GOVERNMENT OF GOA**  
**WATER RESOURCES DEPARTMENT**  
**S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY**  
**Gogol - Margao - Goa.**

No. WRD / WD XI / SDIII / TECH/ W.F. 98-Oct-2023/2024-25/418

dated: 14/03/2024

Name of the Work: Improvement and Strengthening of bunds at Corjem fields from Sy.No. 108/2 to from 101/1 to Sy.No. 101/19 in Curtorim Constituency.

Sample Sent by: Assistant Engineer, SD III, WD II, WRD, Fatorda -Goa

Letter No: No. WRD/SD III/ WD II/F.17/ /2024-25.

Dated:- 11/3/2024

Received on: 11/3/2024

Date of Testing 13-03-2024

**REPORT**

Sr No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F. 98/01/2023	Coarse Sand	FM Silt & Clay Grading	2.452 1.70% Zone III	2.3 to 3.1 Upto 5% I to III Zone	....
F.98/02/2023	Aggregate-20 mm	Grading	...	As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
F. 98/03/2023	Aggregate- 10 mm	Grading	...	As per IS-383-1970 (Re-affirmed in 1990)	

Junior Engineer

Assistant Engineer

- Copy submitted to
- 1) Assistant Engineer, SD III, WD II , WRD, Fatorda-Goa.
  - 2) Executive Engineer, WD XI, WRD, Rawanfond-Goa.
  - 3) Executive Engineer, WD II, WRD, Rawanfond -Goa.
  - 4) The Surveyor of Works, Quality Control, C.P.O., Water Resources Dept., Sinchai Bhavan, Alto Porvorim-Goa.
  - 5) Office File.