

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / TECH / WF.171-Oct-2023 /56 /2024-25.

Dated: 24/04/24

Name of the Work: Construction of protection wall near Dr. Gudinho House near Holy Spirit Church at Modsai in Fatorda Constituency.

Sample Sent by: Assistant Engineer , SD III, WD III , WRD , Gogol- Margao - Goa.

Letter No: No.338/SD III/ WD III/ WRD/24-25/31.

Dated:- 23-04-2024

Received on: 23-04-2024

Date of Testing 24-04-2024

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.171/01/2023	Coarse Sand	FM Silt & Clay Grading	2.378 1.80% Zone III	2.3 to 3.1 Upto 5% Zone I to III	
F. 171/02/2023	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend
F.171/03/2023	Aggregate- 10 mm	Grading		As per IS-383:2016	20mm & 10 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

- Copy submitted to
- 1) Assistant Engineer, SD III, WD III, WRD, Gogol- Margao- Goa.
 - 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
 - 3) The Executive Engineer, Works Division III, WRD, Ponda- Goa.
 - 4) The Surveyor of Works,Quality Control, C.P.O.,Water Resources Dept., Sinchai Bhavan,Alto Porvorim-Goa.
 - 5) Office File