

**GOVERNMENT OF GOA**  
**WATER RESOURCES DEPARTMENT**  
**S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY**  
**Gogol - Margao - Goa.**

No. WRD / WD XI / SDIII / TECH / WF. 24-Oct-2022 / 58 /2022-23.

Dated: 07/12/2022

Name of the Work: Construction of protection wall and Improvement to the nallah in Sy.No. 6/3 in Village Verna in Nuvem Constituency.

Sample Sent by :- Assistant Engineer, SD I, WD II , WRD, Rawanfond- Goa.

Letter no:- No. WRD/SD I/WD II/ F.Esst/488/2022-23.

Dated:- 15-11-2022.

Received on: 24-11-2022

Date of Testing:

26-11-2022

**REPORT**

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F. 24/01/2022	Coarse Sand	FM Silt & Clay Grading	2.946 2.00% Zone III	2.3 to 3.1 Upto 5% I to III Zone	
F. 24/02/2022	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate nominal size blend
F. 24/03/2022	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	20mm & 10 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD I, WD II, WRD, Rawanfond- Goa.
- 2) The Executive Engineer, Works Division II, WRD, Rawanfond, Goa.
- 3) Executive Engineer, WD XI, WRD, Rawanfond -Goa.
- 4) Office File.