## **GOVERNMENT OF GOA** WATER RESOURCES DEPARTMENT S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY

Gogol - Margao - Goa. No. WRD / WD XI / SDIII /TECH /WF. 117-Oct-2024 / 06 / 2025-26. dated: 02/04/25

Name of the Work: Improvement of lake near Datta Mandir in Sy.No. 91/2 at Dattawadi in V.P. Sanvordem in Sanvordem Constituency.

Assistant Engineer, SD I, WD XII, WRD, Pajimol- Sanguem- Goa. Sample Sent by:

Letter No: WRD/SD I/WD XII/F. 47/584/2024-25. Dated: 28-03-2025

Received on: Date of Testing 2/4/2025 29-03-2025

## **REPORT**

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
		FM	2.796	2.3 to 3.1	
F. 117/01/2024	Coarse Sand	Silt & Clay	3.80%	Upto 5%	
		Grading	Zone III	I to III Zone	
		FM	3.066	2.3 to 3.1	
F. 117/02/2024	Metal Sand	Silt & Clay	3.70%	Upto 5%	
		Grading	Zone II	I to III Zone	
F. 117/03/2024	Aggregate-20 mm	Grading		As per IS-383-1970	To get the 20mm graded
				(Re-affirmed in 1990)	aggregate nominal size blend
F. 117/04/2024	Aggregate- 10 mm	Grading		As per IS-383-1970	20mm & 10 mm metal
				(Re-affirmed in 1990)	in 1:1 proportion.

Junior Engineer

**Assistant Engineer** 

Copy submitted to 1) Assistant Engineer, SD I, WD XII, WRD, Pajimol-Sanguem-Goa.

- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) The Executive Engineer, Works Division XII, WRD, Gogol-Margao-Goa.
- 4) The Surveyor of Works, Quality Control, C.P.O., Water Resources Dept., Sinchai Bhavan, Alto Porvorim-Goa.
- 5) Office File.