

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII /TECH /WF.No. 87-Oct-2022 /92 / 2023-24. dated:06/05/2023

Name of the Work: Improvement and Development and to the Swami Bandhara at Pallolem in ward No. X in Canacona Municipal Council.

Sample Sent by: Assistant Engineer, SD II, WD XI, WRD, Canacona -Goa

Letter No: No.WRD/SD II/WDXI/ F.8/23/2023-24.

Dated:- 4/5/2023

Received on: 4/5/2023

Date of Testing 6/5/2023

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.78/01/2022	Coarse Sand	FM Silt & Clay Grading	2.368 2.00% Zone III	2.3 to 3.1 Upto 5% I to III Zone	
F.78/03/2022	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
F.78/04/2022	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD II, WD XI, WRD, Canacona-Goa.
- 2) Executive Engineer, WD XI, WRD, Rawanfond-Goa.
- 3) The Surveyor of Works, Quality Control, C.P.O., Water Resources Dept., Sinchai Bhavan, Alto Porvorim-Goa.
- 4) Office File.