## GOVERNMENT OF GOA OFFICE OF THE ASSISTANT ENGINEER SUB DIVISION III (SOUTH), QUALITY CONTROL LABORATORY, WATER RESOURCES DEPARTMENT, GOGAL, MARGAO- GOA.

## PLEASE FIND THE TEST RESULTS OF CEMENT AS DETAILED BELOW:

Name of work:-Improvement and strengthening of bund in Sy.No. 172 in Village Chinchinim in Velim Constituency.

Type of Cement: Ordinary Portland cement Brand / Grade: JSW/43 grade

Source of receipt: Assistant Engineer, SD I, WD II, WRD, Rawanfond- Goa.

Ref. Letter No: WRD/SD I/ WD II/F. Estt/55/2021-22 .Dated: 21-04-2021

**Qty. Represented:** 

L.S. No: 412/2021

## **Physical Properties**

Sr.	Description	Test results	Requirements as per I.S.
No	-		
1	Fineness. (% retained on 9		Not more than 10%
	micron sieve)	3 %	
2	Setting Time in (Minutes)		
	iii) Initial	186 minutes	Not less than 30 Min
	iv) Final.	294 minutes	Not more than 600 Min.
3	Minimum Com Strength Kg/Cm <sup>2</sup>		
	i) 72 hrs. ±1 hrs.	390.00 Kg/cm2	Not less than230.0Kg/cm2
	ii) 168 hrs. ±2hrs	493.33 Kg/cm2	Not less than 330.0Kg/cm2
	iii) 672 hrs. ±4 hrs	546.66 Kg/cm2	Not less than 430.0Kg/cm2
4	Consistency of cement.	28 %	

To,

The Asst. Engineer.SD I, WD II, WRD, Rawanfond, Navelim- Goa.

C.W.C. Submitted to:

2. The Exe. Eng. W.D. II, WRD, Gogol- Rawanfond, Navelim- Goa.

3. Office file.

**Junior Engineer** 

## Assistant Engineer.