## GOVERNMENT OF GOA OFFICE OF THE ASSISTANT ENGINEER SUB DIVISION III (SOUTH), QUALITY CONTROL LABORATORY, WATER RESOURCES DEPARTMENT, GOGAL, MARGAO- GOA.

## PLEASE FIND THE TEST RESULTS OF CEMENT AS DETAILED BELOW:

Name of work:- Re- Construction of pipe culvert with RCC slab at Ghodegal Ambaulim in Cuncolim Constituency.

Type of Cement: Ordinary Portland cement Brand / Grade: ACC /43 grade

Source of receipt: Assistant Engineer, SD III, WD XIV, WRD, Cuncolim-Goa.

**Ref.** Letter No: WRD/SD III/WD XIV/ W.F.10/2021-22/204. **Dated:** 03-01-2022.

**Qty. Represented:** 

L.S. No: F.61/4/2021

## **Physical Properties**

Sr.	Description	Test results	Requirements as per I.S.
No	•		
1	Fineness. (% retained on 9		Not more than 10%
	micron sieve)	3%	
2	Setting Time in (Minutes)		
	xxiii) Initial	188 minutes	Not less than 30 Min
	xxiv) Final.	284minutes	Not more than 600 Min.
3	Minimum Com Strength Kg/Cm <sup>2</sup>		
	i) 72 hrs. ±1 hrs.	386.66Kg/cm2	Not less than 230.0Kg/cm2
	ii) 168 hrs. ±2hrs	483.33Kg/cm2	Not less than 330.0Kg/cm2
	iii) 672 hrs. ±4 hrs	583.33 Kg/cm2	Not less than 430.0Kg/cm2
4	Consistency of cement.	28%	

To,

The Asst. Engineer.SD III, WD XIV, WRD, Cuncolim-Goa.

C.W.C. Submitted to:

- 2. The Exe. Eng. W.D. XIV, WRD, Rawanfond–Goa.
- 3. Office file.

Junior Engineer

Assistant Engineer.