## GOVERNMENT OF GOA OFFICE OF THE ASSISTANT ENGINEER SUB DIVISION III (SOUTH), QUALITY CONTROL LABORATORY, WATER RESOURCES DEPARTMENT, GOGAL, MARGAO- GOA.

## PLEASE FIND THE TEST RESULTS OF CEMENT AS DETAILED BELOW:

Name of work:-Protection wall in Sy.No. 417 in Village Chinchinim in Velim Constituency.

Type of Cement: Ordinary Portland cement Brand / Grade: Dalmia

Source of receipt: Assistant Engineer, SD I, WD II, WRD, Rawanfond- Goa.

**Ref.** Letter No: WRD/SD I/WD II/F.Estt/907/2021-22. Dated: 24-11-2021.

**Qty. Represented:** 

**L.S. No:** F.116/04/2021

## **Physical Properties**

Sr.	Description	Test results	Requirements as per I.S.
No			
1	Fineness. (% retained on 9		Not more than 10%
	micron sieve)	3 %	
2	Setting Time in (Minutes)		
	xxv) Initial	178 minutes	Not less than 30 Min
	xxvi) Final.	292 minutes	Not more than 600 Min.
3	Minimum Com Strength Kg/Cm <sup>2</sup>		
	i) 72 hrs. ±1 hrs.	363.33 Kg/cm2	Not less than 230.0 Kg/cm 2
	ii) 168 hrs. ±2hrs	436.66 Kg/cm2	Not less than 330.0Kg/cm2
	iii) 672 hrs. ±4 hrs	566.66Kg/cm2	Not less than 430.0Kg/cm2
4	Consistency of coment	28 %	
4	Consistency of cement.	20 70	

To,

The Asst. Engineer.SD I, WD II, WRD, Rawanfond - Goa.

C.W.C. Submitted to:

- 2. The Exe. Eng. W.D. XI, WRD, Rawanfond-Goa.
- 3. Office file.

**Junior Engineer** 

**Assistant Engineer.**