## GOVERNMENT OF GOA OFFICE OF THE ASSISTANT ENGINEER SUB DIVISION III (SOUTH), QUALITY CONTROL LABORATORY, WATER RESOURCES DEPARTMENT, GOGAL, MARGAO- GOA.

## PLEASE FIND THE TEST RESULTS OF CEMENT AS DETAILED BELOW:

**Name of work:-**Construction of Protection wall in Sy.No. 69/4 at Rachol in Curtorim Constituency.

Type of Cement: Ordinary Portland cement Brand / Grade: Jyoti /43 grade

**Source of receipt:** Assistant Engineer, SD I, WD II, WRD, Rawanfond-Goa.

**Ref.** Letter No: WRD /SD I/WD II/F. Estt /528 / 2021-22. **Dated:** 09-11-2021.

**Qty. Represented:** 

L.S. No: F.09/04/2021

## **Physical Properties**

Sr.	Description	Test results	Requirements as per I.S.
No	_		
1	Fineness. (% retained on 9		Not more than 10%
	micron sieve)	4%	
2	Setting Time in (Minutes)		
	iii) Initial	182minutes	Not less than 30 Min
	iv) Final.	294minutes	Not more than 600 Min.
3	Minimum Com Strength Kg/Cm <sup>2</sup>		
	i) 72 hrs. ±1 hrs.	313.33Kg/cm2	Not less than 230.0 Kg/cm2
	ii) 168 hrs. ±2hrs	420.00 Kg/cm2	Not less than 330.0 Kg/cm2
	iii) 672 hrs. ±4 hrs	533.33 Kg/cm2	Not less than 430.0 Kg/cm2
4	Consistency of cement.	28 %	

To.

The Asst. Engineer.SD I, WD II, WRD, Rawanfond-Goa.

C.W.C. Submitted to:

- 1. The Exe. Eng. W.D.XI, WRD, Aquem Baixo- Goa.
- 2. Office file.

**Junior Engineer** 

**Assistant Engineer.**