GOVERNMENT OF GOA

WATER RESOURCES DEPARTMENT

S.D.III. (C.P.O) QUALITY CONTROL LABORATORY

GOGAL, MARGAO-GOA

NO: WRD /WD XI / SD III/ F.59/W.F. 18/2020 / **189** / 2020-21

Dated:05-01-2021

Name of the Work: Protection to nallah sides in the Sy.No. 44/2 and 36/1 in the said property at Shirshirem Borim of Shiroda Constituency.(3rd call)

REQUISITION DETAILS: NO: WRD / WD XI / SD IV/ WF. 416 / 26 / 2020-21. Dat

Dated:-24-12-2020

SAMPLE SENT BY: Assistant Engineer, Sub. Div. IV, Works Div. II, WRD, Ponda-Goa.

SAMPLE RECEIVED ON: 29-12-2020

TYPE OF SAMPLE: Latrite boulders

STRENGTH REQUIRED:

TESTING DATE: 04-01-2021

TESTED BY: Junior Engineer

AUTHORISED BY:

AE, SD III, QC.

AGENCY NAME:

Sr. No:	SAMPLE NUMBER	Comp. strength in Kg/sq.cm.	AVERAGE Kg/sq.cm
1	79	37.84	
2	80	39.74	
3	81	42.78	40.01
4	82	38.02	
5	83	41.67	

Junior Engineer

Assistant Engineer

To,

Assistant Engineer, Sub- Div. IV, Works Div. XI, WRD, Ponda- Goa.

Copy Submitted To:

- 1. Executive Engineer, Works Div. XI, WRD, Rawanfond-Goa.
- 2. Office File No: F-59