GOVERNMENT OF GOA

WATER RESOURCES DEPARTMENT

S.D.III, WORK DIVISION XI, QUALITY CONTROL

GOGAL, MARGAO-GOA

NO: WRD / WD XI / SD III/ F.59 / W.F. 26/2020 / **212** / 2020-21 Dated: 23-01-2021

Name of the Work: Improvement to nallah from Kapadshe to Thall in V.P.Shiroda in Ponda Taluka (2 nd Call).

REQUISITION DETAILS: NO: WRD / WD XI / SD IV/ F. 300 / 63/ 2020-21. Dated:-20-01-2021

SAMPLE SENT BY: Assistant Engineer, Sub. Div. IV, Works Div. XI, WRD, Ponda- Goa.

SAMPLE RECEIVED ON: 20-01-2021

TYPE OF SAMPLE: Latrite boulders

STRENGTH REQUIRED:

TESTING DATE: 23-01-2021

TESTED BY: Junior Engineer AUTHORISED BY: AE, SD III, QC.

AGENCY NAME:

Sr. No:	SAMPLE NUMBER	Comp. strength in Kg/sq.cm.	AVERAGE Kg/sq.cm
1	127	37.50	
2	128	42.78	
3	129	41.67	40.13
4	130	38.71	
5	131	40.00	

Junior Engineer

Assistant Engineer

TΛ

Assistant Engineer, Sub- Div. IV, Works Div. XI, WRD, Ponda- Goa.

Copy Submitted To:

- 1. Executive Engineer, Works Div. XI, WRD, Rawanfond-Goa.
- 2. Office File No: F-59