

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III. (C.P.O) QUALITY CONTROL LABORATORY

Gogol - Margao - Goa.

No. WRD / CPO / SDIII / F.59 / / 2019-20 dated: - 11 -2019.

Name of the Work :- Improvement to Drainage system from Railway bridge to Belabai road junction at Orulem in Vasco Constituency (Phase III).

Sent by / Collected by :- Assistant Engineer, SD II, WD II, WRD, Gogol, Goa.

Letter No: WRD/WD II/SD II/F.03/164/2019-20

Dated:- 6/11/2019

Received on: 15/11/2019

Date of Testing: 18/11/2019

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
4648/19	Coarse Sand	FM Silt & Clay Grading	2.878 2.50% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
4649/19	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate nominal size blend
4650/19	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	20mm & 10 mm metal in 1:1 proportion.
4651/19	Metal Sand	FM Silt & Clay Grading	3.093 4.80% Zone I	2.3 to 3.1 Upto 5% I to III Zone	

Sandip Parab
Junior Engineer

Pravin C Parsekar
Assistant Engineer

- Copy submitted to
- 1) Assistant Engineer, SD II, WD II, WRD, Gogol -Goa.
 - 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
 - 3) Executive Engineer, WD II, WRD, Rawanfond -Goa.
 - 4) Office File.