GOVERNMENT OF GOA

WATER RESOURCES DEPARTMENT

S.D.III, WORK DIVISION XI, QUALITY CONTROL

GOGAL, MARGAO- GOA

NO: WRD / WD XI / SD III/ F.59 / W.F. 89/2020-21 / 68 / 2021-22 Dated:07/07/2

Name of the Work: - Construction of protection wall to nallah near sub- yard of Agriculture marketing board in V.P. Curti of in Ponda Taluka

REQUISITION DETAILS: NO: WRD / WD XI / SD IV/ F. cf / 143/ 2021-22. Dated:-02-07-202.

SAMPLE SENT BY: Assistant Engineer, Sub. Div. IV, Works Div. XI, WRD, Ponda-Goa.

SAMPLE RECEIVED ON: 2/7/2021

TYPE OF SAMPLE: Latrite boulders

STRENGTH REQUIRED:

TESTING DATE: 6/7/2021

TESTED BY: Junior Engineer AUTHORISED BY: AE, SD III, QC.

AGENCY NAME:

Sr. No:	SAMPLE NUMBER	Comp. strength in Kg/sq.cm.	AVERAGE Kg/sq.cm
1	489	37.50	
2	490	40.00	
3	491	37.50	38.50
4	492	40.00	
5	493	37.50	

Junior Engineer

Assistant Engineer

To,

Assistant Engineer, Sub- Div. IV, Works Div. XI, WRD, Ponda- Goa.

Copy Submitted To:

- 1. Executive Engineer, Works Div. XI, WRD, Rawanfond-Goa.
- 2. Office File No: F-59