

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59 / WF.19/2021 / / 2020-21. dated:

Name of the Work: Improvement of culvert across Bhiunsa Khariz and Dandora bandh under jurisdiction of Cuncolim Municipality in Salcete Taluka.

Sample Sent by: Assistant Engineer, SD III, WD III, WRD, Gogol- Margao-Goa

Letter No: No.261/SD III/WDIII/WRD/2020-21/338

Dated:- 14-01-2021

Received on: 15-01-2021

Date of Testing: 16-01-2021

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
85/2021	Coarse Sand	FM Silt & Clay Grading	2.552 2.30% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
86/2021	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend
87/2021	Aggregate- 10 mm	Grading		As per IS-383:2016	20mm & 10 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD III, WD III, WRD, Gogol- Margao-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) Executive Engineer, WD III, WRD, Ponda-Goa.
- 4) Office File.