

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

/No. WRD / WD XI / SDIII / F.59 / WF.36/2021 / 219 / 2020-21. dated: 17/02/2021

Name of the Work: Improvement to Tolleaband lake sluice gate and outlet at Tolleaband of Village Chinchinim in Velim Constituency.

Sample Sent by: Assistant Engineer, SD I, WD II, Rawanfond WRD, -Goa

Letter No: No.WRD/SD I/ WD II/F.Estt/833/2020-21

Dated:- 15-02-2021

Received on: 15-02-2021

Date of Testing: 17-02-2021

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
173/2021	Coarse Sand	FM Silt & Clay Grading	2.606 1.40% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
174/2021	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
175/2021	Aggregate- 10 mm	Grading		As per IS-383:2016	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD I, WD II, WRD, Rawanfond-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) The Executive Engineer, Works Division II, WRD, Rawanfond- Goa.
- 4) Office File.