

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59 / WF.22/2021 / 156 / 2021-22.

dated: 08/12/2021

Name of the Work: Urgent Repairs to old canal outlet and providing Kolhapur type M.S. Gates to Firguni band in V.P. Kirlepal - Dabal in Sanvordem Constituency.

Sample Sent by: Assistant Engineer, SD III, WD XII, WRD, Dharbandora -Goa

Letter No: No. WRD/WD XII/ SD III/ F.1/2021-22/121.

Dated:- 8/11/2021

Received on: 2/12/2021

Date of Testing: 06-12-2021

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.22/1/2021	Coarse Sand	FM Silt & Clay Grading	2.946 2.00% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
F.22/2/2021	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
F.22/3/2021	Aggregate- 10 mm	Grading		As per IS-383:2016	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD III, WD XII, WRD, Dharbandora-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) Executive Engineer, WD XII, WRD, Gogol- Margao-Goa.
- 4) Office File.