

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59 / WF.27/2021 / 160 / 2021-22.

dated: 10/12/2021

Name of the Work: Annual maintenance and repairs works of Sanvordem branch of Dist. D1 from Ch.0.000 kms to Ch.2.40 kms for the year 2021-22.

Sample Sent by :- Assistant Engineer, SD I, WD XIV , WRD, Quepem- Goa.

Letter no:- No. WRD/ WD XIV/SD I/ W.F. 1/2021-22/165

Dated:- 09-12-2021

Received on: 9/12/2021

Date of Testing: 10-12-2021

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.27/1/2021	Coarse Sand	FM Silt & Clay Grading	3.044 3.80% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
F.27/2/2021	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate nominal size blend
F.27/3/2021	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	20mm & 10 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD I, WD XIV, WRD, Quepem- Goa.
- 2) The Executive Engineer, Works Division XIV, WRD, Rawanfond, Goa.
- 3) Executive Engineer, WD XI, WRD, Rawanfond -Goa.
- 4) Office File.