## GOVERNMENT OF GOA WATER RESOURCES DEPARTMENT S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY

**Gogol - Margao - Goa.** No. WRD / WD XI / SDIII / F.59/W.F. 44/2021 /183 / 2021-22 .

dated: 27/12/2021

Name of the Work: Annual maintenance & Repairs works of Assolda branch & Xelvona branch from Ch.0.00 kms to Ch. 2.64 kms for the year 2021-22.

Sample Sent by: Assistant Engineer, SD I, WD XIV, WRD, Quepem -Goa

Letter No: No. WRD/WD XIV/SD I/WF.7/2021-22/179.

Dated:- 21-12-2021

Received on:

21-12-2021

Date of Testing: 27-12-2021

**REPORT** 

			<b>NEI UNI</b>		
Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
		FM	2.702	2.3 to 3.1	
F.45/01/2021	Coarse Sand	Silt & Clay	1.60%	Upto 5%	
		Grading	Zone II	l to III Zone	
		FM	2.030	< 2.3	
F.45/02/2021	Fine Sand	Silt & Clay	1.80%	Upto 5%	
		Grading	Zone IV	Zone IV	
F.45/03/2021	Aggregate-20 mm	Grading		As per IS-383-1970	To get the20mm graded
				(Re-affirmed in 1990)	aggregate nominal size blend
F.45/04/2021	Aggregate- 10 mm	Grading		As per IS-383-1970	20mm & 10 mm metal
				(Re-affirmed in 1990)	in 1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to 1) Assistant Engineer, SD I, WD XIV, WRD, Quepem-Goa.

2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.

3) The Executive Engineer, Works Division XIV, WRD, Rawanfond- Goa.

4) Office File.