GOVERNMENT OF GOA WATER RESOURCES DEPARTMENT S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY

Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59/W.F. 64/2021 /206 / 2021-22 . dated: 06/01/2022

Name of the Work: Construction of Bund & Retaining wall in Sy.No. 53/4 on River Sal at Cavelossim in Benaulim Constituency.

Sample Sent by: Letter No:	Assistant Engineer, SD I, WD II, WRD, Rawanfond- Goa. WRD / SD I/ WD II/ F.Estt/661/2021-22.			Dated:- 4/1/2022	
Received on: 4/1/2022		Date of Testing: 06-			
<u>REPORT</u>					
Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
		FM	2.570	2.3 to 3.1	
F.64/01/2021	Coarse Sand	Silt & Clay	1.40%	Upto 5%	
		Grading	Zone II	l to III Zone	
F.64/02/2021	Aggregate-20 mm	Grading		As per IS-383-1970	To get the20mm graded
				(Re-affirmed in 1990)	aggregate nominal size blend
F.64/03/2021	Aggregate- 10 mm	Grading		As per IS-383-1970	20mm & 10 mm metal
				(Re-affirmed in 1990)	in 1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to 1) Assistant Engineer, SD I, WD II, WRD Rawanfond- Goa.

2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.

3) Executive Engineer, WD II, WRD, Rawanfond-Goa.

4) Office File.