## GOVERNMENT OF GOA OFFICE OF THE ASSISTANT ENGINEER SUB DIVISION III (SOUTH), QUALITY CONTROL LABORATORY, WATER RESOURCES DEPARTMENT, GOGAL, MARGAO- GOA.

## PLEASE FIND THE TEST RESULTS OF CEMENT AS DETAILED BELOW:

Name of work:-Construction of protection wall of nallah from Satish Pednekar house to Hari Tuenkar house in Malbar bund V.P. Anjuna Caisua in Siolim Constituency.

Type of Cement: Ordinary Portland cement Brand / Grade: JK /43 grade

Source of receipt: Assistant Engineer, SD I, WD I, WRD, Porvorim-Goa.

**Ref. Letter No:** WRD/ MI/WD I/SD I/F.57/2020-21/459. **Dated:** 13-11-2020

**Qty. Represented:** 

L.S. No: 30/20

## **Physical Properties**

Sr.	Description	Test results	Requirements as per I.S.
No			
1	Fineness. (% retained on 9	4 %	Not more than 10%
	micron sieve)		
2	Setting Time in (Minutes)		
	i) Initial	160 minutes	Not less than 30 Min
	ii) Final.	288 minutes	Not more than 600 Min.
3	Minimum Com Strength Kg/Cm <sup>2</sup>		
	i) 72 hrs. ±1 hrs.	366.66 Kg/cm2	Not less than 230.0 Kg/cm2
	ii) 168 hrs. ±2hrs	486.66 Kg/cm2	Not less than 330.0Kg/cm2
	iii) 672 hrs. ±4 hrs	543.33 Kg/cm2	Not less than 430.0Kg/cm2
4	Consistency of cement.	29 %	

To,

The Asst. Engineer.SD I, WD I, WRD, Porvorim-Goa.

C.W.C. Submitted to:

- 2. The Exe. Eng. W.D. I, WRD, Porvorim-Goa.
- 3. Office file.

**Junior Engineer** 

Assistant Engineer.