QUALITY CONTROL LABORATORY WATER RESOURCES DEPARTMENT

<u>Test Report No</u>.: WRD/Q.C./F.6-3/Soil. T- 1526,1527 & 1528 /Lab/**290**/2021-22 Dated: 07/ 02 /2022.

Laboratory: Bicholim Sub Division: V (QC)/WRD/Bicholim

Sub:Strengthening to the bund "Cava Casana" at Chorao in Tiswadi Taluka.Ref to requisition No.:3-Tech/F.4(Tis)/05/SCD/D.Agri/2020-21/894dt:-21/01/2022Oty. Received:½ bag Soil.Date of Receipt:25/01/2022Tested on:01,02 & 03/02/2022Sample of:SoilO.S. No.:7551,7552 & 7553/SSLab. Sample No.:2825Ref to IS/CPWD Specification:IS:2720, Part IV, V,1985Sample of:SoilO.S. No.:7551,7552 & 7553/SSLab. Sample No.:2825Ref to IS/CPWD Specification:IS:2720, Part IV, V,1985

R E P O RT 01 OF 1

 Sr. No.	Description of sample	Tested for	Results	Max./Min. value per	rmissible	Remarks	
1.	Soil:	I) <u>Plasticity I</u>	<u>ndex</u> .				
	(L.S.No. 2825)						
		Liquid Limi	t :- 37.75 %				
		Plastic Limi	t : - 32.88 %				
		Plasticity In	dex : - 4.87%				
		II. <u>Sieve An</u>	<u>alysis</u>				
		a) Silt and	Clay by Sieve Analysis	:- 26.20%			
		b) Fine San		:- 1.40%			
		c) Medium	Sand	:- 25.40%			
		d) Coarse S	and	:- 13.80%			
		e) Gravel		:- 33.20%			

Copy to: 1. The Assistant Engineer, o/o The Executive Engineer, Soil Conservation Division, Directorate of Agriculture, Krishi Bhavan, Tonca Caranzalem - Goa. 2. Q.C. Lab file 3. Bill File.

Junior Engineer

Assistant Engineer