

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59. W.F. 30/2021 /220 / 2020-21

dated: 08/02/2021

Name of the Work: Construction of Protection Wall to the land bearing chalta No. 221of P.T. Sheet No. 3 Margao city at

Aquem, Margao

Sample Sent by :- Assistant Engineer, SD III, WD III, WRD, Gogol- Margao- Goa.

Letter no:- No. WRD/ SD III/WD III/ F.260/2020-21/354.

Dated:- 01-02-2021

Received On: 01-02-2021

Date of Tesing: 08-02-2021

REPORT

Sr. No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
141/2021	Coarse Sand	FM Silt & Clay Grading	2.608 1.40% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
142/2021	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
143/2021	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SDIII, WD III,WRD, Gogol- Margao, Goa.
- 2) The Executive Engineer, Works Division III, WRD, Ponda, Goa.
- 3) Executive Engineer, WD XI, WRD, Rawanfond -Goa.
- 4) Office File.