## GOVERNMENT OF GOA OFFICE OF THE ASSISTANT ENGINEER SUB DIVISION III (SOUTH), QUALITY CONTROL LABORATORY, WATER RESOURCES DEPARTMENT, GOGAL, MARGAO- GOA.

## PLEASE FIND THE TEST RESULTS OF CEMENT AS DETAILED BELOW:

Name of work:- Anti Sea Erosion Wall from Vinod Sawant house to Audumbar

Sirsaikar house in V.P Assagao in Siolim Constituency.

**Type of Cement:** Ordinary Portland cement **Brand / Grade:** Ramco/43 grade

Source of receipt: Assistant Engineer, SD I, WD I, WRD, Porvorim, Goa

**Ref. Letter No:** WRD/ M.I/WD I/S.D I/F.57/19-20/335 **Dated:** 02-12-2019

**Qty. Represented:** 

L. S. No: 4710/19

## **Physical Properties**

Sr.	Description	Test results	Requirements as per I.S.
No			
1	Fineness. (% retained on 9		Not more than 10%
	micron sieve)	4 %	
2	Setting Time in (Minutes)		
	i) Initial	182 minutes	Not less than 30 Min
	ii) Final.	293 minutes	Not more than 600 Min.
3	Minimum Com Strength Kg/Cm <sup>2</sup>		
	i) 72 hrs. $\pm$ 1 hrs.	343.33 Kg/cm2	Not less than 230.0 Kg/cm2
	ii) 168 hrs. ± 2 hrs	456.66/cm2	Not less than 330.0 Kg/cm2
	iii) 672 hrs. $\pm$ 4 hrs	583.33Kg/cm2	Not less than 430.0 Kg/cm2
4	Consistency of cement.	29 %	

To.

The Assistant Engineer, SD I, WD I, WRD, Porvorim, Goa

C.W.C. Submitted to:

- 1. The Exe. Eng. W.D.XI, WRD, Rawanfond-Goa.
- 2. Office file.

Dhananjay R. Nagvenkar Technical Assistant

Pravin C Parsekar Assistant Engineer.