

GOVERNMENT OF GOA
SD III (QC) , WRD, GOGAL, MARGAO- GOA.

NAME OF THE WORK: Urgent repairs to Retaining wall of SIP Main Canal at CH 18.95 Kms in Ambaulim village.

SAMPLE SENT BY: AE, SD III, WD XIV, WRD, Cuncolim- Goa.

NAME OF THE AGENCY

TESTING PERIOD

28 days.

REPORT NO	SAMPLE NOS.	CASTING DATE	TESTING DATE	LOCATION OF SAMPLE	MIX PROPORTION	REQUIRED STRENGTH	Comp sth in Kg/cm2	Avg. Comp Kg/cm2	LETTER No / DATED
	58						248.88		
1	59	22-10-2019	19-11-2019	Retaining wall	1.2.4	210 kg/cm2	253.33	247.40	No.WRD/SD III/WD XIV /WF.3/130/2019-20
	60						240.00		DATED: 28-10-2019
	61						244.44		
2	62	22-10-2019	19-11-2019	Retaining wall	1.2.4	210 kg/cm2	248.88	248.88	do
	63						253.33		
	64						257.77		
3	65	23-10-2019	20-11-2019	Retaining wall	1.2.4	210 kg/cm2	262.22	256.29	do
	66						248.88		
	67						253.33		
4	68	23-10-2019	20-11-2019	Retaining wall	1.2.4	210 kg/cm2	257.77	257.77	do
	69						262.22		

Joaquim Antao
JUNIOR ENGINEER.

Pravin C Parsekar
ASSISTANT ENGINEER