

GOVERNMENT OF GOA  
QUALITY CONTROL LABORATORY  
WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 6979 / Lab / **158** / 2019 - 20      Dated:- 04 /06 / 2019      Laboratory : Bicholim - Goa.

Sub Division V (QC)/WRD/ Bicholim- Goa.

**Name of Work: - Stabilization unstable Hill slope for the hill behind St. Mary High Scool at Altinho , Mapusa , Bardez Goa.**

Ref. to Requisition no.: SDII/WDI/WRD/ F.24 /2019-20/119      dated :- 31 / 05 /2019.

Qty. Recived. : 01 Set of cube      Date of Receipt: - 03 / 06 / 2019.      Tested on: - 03 / 06 /2019.      Ref to CPWD :2002, Vol. I

Sample: Cube **M- 25**      O.S No. :-2037 /SS      Lab. Sample No.: 5031      Tested By: Mrs. S.B. Naik Shirodkar. J.E.

**REPORT PAGE 01 OF 01**

SR.N O.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Reinforced Cement concrete cube of mix <b>M - 25</b> , cast on 06 / 05 /2019, For Stem of cantilever retaining wall . Quantity represents 14.40 Cum	28 <sup>th</sup> day compressive strength	292.22	Kg/Cm2	290 kg/cm2	3.37	Excat location of work done is not specified.
			328.46	Kg/Cm2			
			278.63	Kg/Cm2			
		<b>Average</b>	<b>299.77</b>	<b>Kg/Cm2</b>			

Copy to: 1. The Assistant Engineer ,SD II,WD I,WRD, Mapusa - Goa.

2. Copy submitted to the Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to the Executive Engineer ,WD I,WRD, Porvorim Goa.

4. QC Lab File.      5. Bill File.

Junior Engineer

Assistant Engineer