

GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 7151 / Lab / **189** / 2019 - 20 Dated:- 14/ 06 / 2019 Laboratory : Bicholim - Goa.
Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work : Construction of Anjuna Distributory taking off at ch. 28.97 km of the Left bank main canal of Tillari Irrigation Project in Siolim & Anjuna Village of Bardez Taluka. Part II :Construction of Rising main and reinstatement of allied structures for Anjuna Distributory from ch.0.00km to ch. 4.50kms in Cucholim and Siolim Village of Bardez Taluka.

Ref. to Requisition No.: WRD /WD VIII / SD III / W F.32 /(PART -II)/2019-20/42 dated :-17 / 05 / 2019.

Qty. Recived. : 01 Set of cube Date of Receipt:- 17/ 05 / 2019. Tested on: - 10 /06/2019 Ref to CPWD :2002, Vol. I

Sample: Cube Mix 1 : 1.5 : 3 O.S No. : 2201/SS. Lab. Sample No.: 4729 Tested By: Mrs. S.B. Naik Shirodkar. J.E.

REPORT PAGE 01 OF 01

SR. NO.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Cement concrete cube of mix 1 : 1.5 : 3 , cast on 13/05/2019, for Anchor block. (S1)	28 th day	294.48	Kg/Cm ²	265.00 Kg/cm ²	14.26	Qty represents - 6.00 Cum.
		compressive strength	305.81	Kg/Cm ²			
			308.08	Kg/Cm ²			
		Average	302.79	Kg/Cm²			

Copy to: 1. The Assistant Engineer , SDIII , WD VIII, WRD, Karaswada, Bardez - Goa.

2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to The Executive Engineer ,WD VIII ,WRD, Karaswada -Bardez - Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer