

GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 7818 & 7834 / Lab / **257** / 2019 - 20 Dated:- 23/ 07 / 2019 Laboratory : Bicholim - Goa.
Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work : Construction of Multi Purpose Cyclone Shelter at Dando Siolim under Survey No. 104/1 of Siolim village in V. P. Siolim - Marna of Bardez Taluka.

Ref. to Requisition No.: SD IV / NCRMP -II (NORTH GOA)/ W D III /WRD / W F.6 /2019-20/ 153 dated :-17 / 07 / 2019.

Qty. Recived. : 02 Sets of cube Date of Receipt:- 18 / 07 / 2019. Tested on:- 18/07/2019 & 19/07/2019 . Ref to CPWD :2002, Vol. I

Sample: Cube Mix 1 : 3 : 6 O.S No. : 2631 & 2647/SS. Lab. Sample No.: 6693 & 6694. Tested By: Mrs. S.B. Naik Shirodkar. J.E.

Cube Test is witnessed by Mr. R. Arjun., representative of M/s . Bagkiya Construction Pvt Ltd, on 18/07/2019.

REPORT PAGE 01 OF 01

SR. NO.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Cement concrete cube of mix 1 : 3 : 6 , cast on 20/06/2019, for Foundation .	28 th day compressive strength	124.59	Kg/Cm ²	100.00 Kg/cm ²	29.88	Qty represents - 24.00 Cum.
			138.18	Kg/Cm ²			
			126.85	Kg/Cm ²			
		Average	129.88	Kg/Cm²			
2	Cement concrete cube of mix 1 : 3 : 6 , cast on 21/06/2019, for Foundation .	28 th day compressive strength	129.12	Kg/Cm ²	100.00 Kg/cm ²	27.61	Qty represents - 23.00 Cum.
			122.32	Kg/Cm ²			
			131.39	Kg/Cm ²			
		Average	127.61	Kg/Cm²			

Copy to: 1. The Assistant Engineer , SD IV , NCRMP - II (North Goa),WD III, WRD, Porvorim - Goa.

2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to The Executive Engineer ,WD III ,WRD, Ponda - Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer