GOVERNMENT OF GOA QUALITY CONTROL LABORATORY WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 9474 / Lab / **12** / 2020 - 21

Dated: 30/04/2020 Laboratory: Bicholim - Goa.

Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work: Widening to Inspection path of RBMC of AIP for approach at Shiroli aqueduct at Keri Sattari Goa.

Ref. to Requisition No.: F.37 /SD I/WD V/AIP/ WRD/2020-21/02 dated :- 22/04 / 2020.

Qty. Recived.: 01 Set of cube Date of Receipt:- 23/04/2020. Tested on: - 28/04/2020. Ref to CPWD: 2009, Vol. I

Sample: Cube Mix 1:2:4 O.S No.: 3562 /SS. Lab. Sample No.: 8580 Tested By: Mrs. S.B. Naik Shirodkar. J.E.

REPORT PAGE 01 OF 01

SR. NO.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.VALUE PERMISSABLE	% ABOVE OR BELOW	REMARK
1	Plain Cement concrete cube of mix 1:2:4, cast on 21/04/2020. For retaining wall at D/S of Shiroli Keri aqueduct.	7 th day compressive strength	158.57	Kg/Cm ²	140.00 Kg/cm ²	8.95	Qty represents - 11.50 Cum.
			154.04	Kg/Cm ²			
			144.98	Kg/Cm ²			
		Average	152.53	Kg/Cm ²			

Copy to: 1. The Assistant Engineer, SDI, WD V, WRD, Keri Sattari - Goa.

- 2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.
- 3. Copy submitted to The Executive Engineer ,WD V ,WRD, Karapur Tisk, Sankhali Goa.
- 4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer