GOVERNMENT OF GOA QUALITY CONTROL LABORATORY WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 2626/ Lab / 164 / 2021 - 22 Dated: -27/ 07 / 2021. Laboratory : Bicholim - Goa.

Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work: Improvement to the Minor 1 & 2 of Lift Irrigation Scheme No.1 at Village Kasarvornem in Pernem Taluka.

Ref. to Requisition No.: SDI/WDVII/WRD/F-355/2021-22/66 Dated :- 25/06/2021.

Qty. Recived. :01 Sets of cube Date of Receipt:- 05/07/2021. Tested on: -23/07/2021 as per due dates. Ref to CPWD :2009, Vol. I

Sample: Cube Mix 1:2:4 O.S No.: 6864/SS. Lab. Sample No.: 2055 Tested By: Mrs. Shirodkar. J.E.

REPORT PAGE 01 OF 01

SR.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Cement concrete cube of mix 1:2:4 , cast on 25/06/2021.P.C.C for Chambers Anchor blocks & thrust block.	28 th day compressive	212.93 226.53	Kg/Cm ² Kg/Cm ²	210.00 Kg/cm ²	4.27	Qty represents -20.00 Cum.
		strength Average	217.47 218.98	Kg/Cm ² Kg/Cm ²			

Copy to: 1. The Assistant Engineer, SD I, WD VII, WRD, Dhargal-Pernem - Goa.

- 2. Copy submitted to The Superintending Engineer, CPO, WRD, Sinchai Bhavan, Porvorim Goa for kind Information.
- 3. Copy submitted to The Executive Engineer, WD VII, WRD, Dhargal-Pernem Goa.
- 4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer