GOVERNMENT OF GOA QUALITY CONTROL LABORATORY WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.75 / Cube -T : 5458 & 5459/ Lab / **185**/ 2022 - 23 Dated:- 04/ 11/ 2022.

Laboratory : Bicholim - Goa.

Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work: Urgent repair for Bastora Minor -2 (Extension) and OR-1 of Calangute Distributory of left Bank Main Canal in Guirim Village of Bardez Taluka.

Ref. to Requisition No.: SD I/WDVIII/WRD/WF.75/2022-23/146 dated:-28/10/2022.

Oty. Recived.: 02 Set of cube Date of Receipt:- 31/10/2022 Tested on: - 01/11/2022 & 03/11/2022 as per due dates. Ref to CPWD: 2009, Vol. I

Sample: Cube Mix 1:2:4 O.S No.: 9451 & 9454/SS. Lab. Sample No.: 5360 & 5361 Tested By: Mrs. S.B. Naik Shirodkar. J.E.

REPORT PAGE 01 OF 01

SR. NO	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Cement concrete cube of mix 1:2:4 , cast on 25/10/2022. PCC for Beds of TO Chambers.	7 th day compressive strength Average	181.22 163.10 167.63 170.65	Kq/Cm ² Kq/Cm ² Kq/Cm ² Kq/Cm ²	140.00 Kg/cm ²	21.89	1. Oty represent -20.00 cum. 2. 28th day test due on 22/11/2022.
2	Cement concrete cube of mix 1:2:4 , cast on 27/10/2022. PCC for Beds of TO Pillar.	7 th day compressive strength	176.69 174.43 165.36 172.16	Kg/Cm ² Kg/Cm ² Kg/Cm ²	140.00 Kg/cm ²	22.97	1.Qty represent -20.00 cum. 2. 28th day test due on 24/11/2022.

Copy to: 1. The Assistant Engineer, SDI, WD VIII, WRD, Karaswada Bardez - Goa.

- 2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.
- 3. Copy submitted to The Executive Engineer, W.D VIII, WRD, Karaswada Bardez Goa.
- 4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer