

GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 175 / Lab / **100** / 2020 - 2021 Dated:- 20 /07 / 2020 Laboratory : Bicholim - Goa.

Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of Work: - Stabilization unstable Hill slope for the hill behind St. Mary High School at Altinho , Mapusa , Bardez Goa.

Ref. to Requisition no.: SDII/WDI/WRD/ F.24 /2020-21/**126** dated :- 14 / 07 /2020.

Qty. Recived. : 01 Set of cube Date of Receipt: - 14 / 07 / 2020. Tested on: - 14 / 07/2020. Ref to CPWD :2009, Vol. I

Sample: Cube **M- 25** O.S No. :- 4065 /SS Lab. Sample No.: 9316 Tested By: Mrs. S.B. Naik Shirodkar, J.E.

Cube test is witnessed by Shri. Sachin Haldankar, representative by Agency M/s . S.P.S. Construction Pvt Ltd, on 14/07/2020.

REPORT PAGE 01 OF 01

SR.N O.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissible	% above or below	REMARK
1	Cement concrete cube of mix M - 25 , cast on 16 /06 /2020, For stem of cantilever retaining wall from ch.17.10 m to 32.25m.	28 th day compressive strength	310.34	Kg/Cm2	290 kg/cm2	5.97	Quantity represents 8.00 Cum
			317.14	Kg/Cm2			
			294.48	Kg/Cm2			
		Average	307.32	Kg/Cm2			

Copy to: 1. The Assistant Engineer ,SD II, WD I, WRD, Mapusa - Bardez - Goa.

2. Copy submitted to the Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to the Executive Engineer ,WD I,WRD, Porvorim Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer