GOVERNMENT OF GOA

QUALITY CONTROL LABORATORY

WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 8257 & 8348/ Lab / **378**/2019 - 20

Dated:-08/01 / 2020 Laboratory : Bicholim- Goa.

Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of Work: - Stabilisation unstable hill slope for the hill behind St. Mary High School at Altinho, Mapusa Bardez - Goa.

Ref. to Requisition no.: SDII/WDI/WRD/ F.24 /2019-20/500 dated :-23/12/2019.

Qty. Recived. : 02 Sets of cube Date of Receipt: 26/12/2019. Tested on: 30/12/2019 & 07/01/2020. Ref to CPWD :2009, Vol. I

Sample: Cube **M-25** Mix O.S No. :1396/AF & 2952/SS Lab. Sa

Lab. Sample No.: 7383 & 7384

Tested By: Mr. Anil. R. Fadte. J.E & Mrs. S.B. Naik Shirodkar. J.E.

SR. NO.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
	Reinforced Cement concrete cube of mix M-25 cast on 02/12/2019. for Stem of Cantilever retaining wall from Ch.17.10 to 32.25 m	28 th day compressive	285.42 294.48	Kg/Cm2 Kg/Cm2	290.00 Kg/Cm ²	3.63	Quantity represents 13.50 Cum.
		strength	321.67	Kg/Cm2			
		Average	300.52	Kg/Cm2			
2	Reinforced Cement concrete cube of mix M-25 cast on 10/12/2019. for Stem of Cantilever retaining wall from Ch.17.10 to 32.25 m	28 th day	328.46	Kg/Cm2	290.00 Kg/Cm ²	9.10	Quantity represents 6.00 Cum.
		compressive	303.55	Kg/Cm2			
		strength	317.14	Kg/Cm2			
		Average	316.38	Kg/Cm2			

REPORT PAGE 01 OF 01

Copy to: 1. The Assistant Engineer ,SD II,WD I,WRD, Mapusa - Goa.

2. Copy submitted to the Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to the Executive Engineer ,WD I,WRD, Porvorim Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer