GOVERNMENT OF GOA

QUALITY CONTROL LABORATORY

WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 8915 / Lab / **455** / 2019 - 20 Dated: 26 /02 / 2020 Laboratory : Bicholim - Goa.

Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of Work: - Stabilization unstable Hill slope for the hill behind St. Mary High Scool at Altinho, Mapusa, Bardez Goa.

Ref. to Requisition no.: SDII/WDI/WRD/ F.24 /2019-20/640 dated :- 22 / 02 /2020.

Qty. Recived. : 01 Set of cube Date of Receipt: - 24 / 02 / 2020. Tested on: - 25 / 02 /2020. Ref to CPWD :2009, Vol. I

Sample: Cube M-25 O.S No. :-3288 /SS Lab. Sample No.: 8043 Tested By: Mrs. S.B. Naik Shirodkar. J.E.

REPORT PAGE 01 OF 01

SR.N O.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Reinforced Cement concrete cube of mix M - 25 , cast on 28 / 01 /2020, For raft slab(Toe & heel) of cantilever retaining wall from ch.32.25 m to 37.35m	28 th day compressive strength	326.20	Kg/Cm2	- 290 kg/cm2	10.66	Quantity represents 14.40 Cum
			301.28	Kg/Cm2			
			335.26	Kg/Cm2			
		Average	320.91	Kg/Cm2			

Copy to: 1. The Assistant Engineer ,SD II,WD I,WRD, Mapusa - Goa.

2. Copy submitted to the Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to the Executive Engineer ,WD I,WRD, Porvorim Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer