GOVERNMENT OF GOA QUALITY CONTROL LABORATORY WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T :1869,1902 / Lab / 73 / 2021 - 22 Dated:- 18 /05/ 2021. Laboratory : Bicholim - Goa. Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work :Desilting of Rivulets /Poi, Agriculture fields and reconstruction of existing sluice in Savat Khazan and khazan field at Shirgao in Bicholim Taluka.

Sub Est.IV:-Reconstruction of sluice (Near Mharingan Temple) in Kharat Khazan at Shirigao village in Bicholim Taluka.

Ref. to Requisition No.: F.36/SDIII/WDVI/WRD/2021-22/22 Dated :- 03/ 05/ 2021.

Qty. Recived. :02 Sets of cube Date of Receipt:- 03/05/2021. Tested on: -04 & 07/05/2021 as per due dates. Ref to CPWD :2009, Vol. I

Sample: Cube Mix PCC 1:2:4 O.S No. :6084,6112/SS Lab. Sample No.: 1399 & 1400 Tested By: Mrs. Shirodkar. J.E.

REPORT PAGE 01 OF 01

SR. NO.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Cement concrete cube of mix 1:2:4 , cast on 27/04/2021. P.C.C. for cut off and bed of sluice gate	7 th day compressive strength	151.77 172.16 181.22	$\frac{\text{Kg/Cm}^2}{\text{Kg/Cm}^2}$	140.00 Kg/cm ²		1)Qty represents -15.00 Cum. 2)28th day test due on 25/05/2021
		Average	168.38	Kg/Cm ²			
2	Cement concrete cube of mix 1:2:4 , cast on 30/04/2021. P.C.C. for cut off and bed of sluice gate	7 th day compressive strength Average	144.98 163.10 156.30 154.79	$\frac{\text{Kg/Cm}^2}{\text{Kg/Cm}^2}$ $\frac{\text{Kg/Cm}^2}{\text{Kg/Cm}^2}$	- 140.00 Kg/cm ²	105/	1)Qty represents -14.00 Cum. 2)28th day test due on 28/05/2021

Copy to: 1. The Assistant Engineer, SD III, WD VI, WRD, Mulgao - Goa.

2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to The Executive Engineer, WD VI, WRD, Bicholim - Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer