GOVERNMENT OF GOA QUALITY CONTROL LABORATORY WATER RESOURCES DEPARTMENT

Test Report No: WRD/QC/F.6-2/Cube -T : 6747/Lab/**36**/2023 - 24 Dated: - 28/04/2023.

Laboratory : Bicholim - Goa. Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work : Construction of Raw Water Pumping Station at Amthane for Dhumacem water treatment Plant and Industrial Estate at Latambarcem.

Ref. to Requisition No : WRD/WDVI/SDI/F.W.247/2022-23/02. Dated :- 04/04/2023.

Qty. Recived : 01 Set of cube Date of Receipt:- 05/04/2023 Tested on:- 26/04/2023 Ref to CPWD :2009, Vol. I

Sample: Cube Mix 1:2:4 O.S No : 728/SS. Lab. Sample No: 6737. Tested By: Mrs. S.B. Naik Shirodkar. J.E.

REPORT PAGE 01 OF 01

SR.N O.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
	Cement concrete cube of mix 1:2:4 , cast on 29/03/2023. PCC for the Dam Top.	28 th day compressive	240.12 249.18	Kg/Cm ² Kg/Cm ²	210.00 Kg/cm ²	19.38	Qty represents - 19.20 Cum.
		strength	262.77	Kg/Cm ²			
		Average	250.69	Kg/Cm ²			

Copy to: 1. The Assistant Engineer , SD I, WD VI, WRD, Bicholim - Goa.

2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to The Executive Engineer, WD VI, WRD, Bicholim - Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer