

GOVERNMENT OF GOA
SD III (QC) , WRD, GOGAL, MARGAO- GOA.

NAME OF THE WORK: Protective wall for nallah in Sy.No. 318, 322 and for Pond in Sy.No. 63 in Village Velim in Velim Constituency.

SAMPLE SENT BY: AE, SD I, WD II, WRD, Rawanfond- Goa.

NAME OF THE AGENCY

TESTING PERIOD

28 days.

| REPORT NO | SAMPLE NOS. | CASTING DATE | TESTING DATE | LOCATION OF SAMPLE | MIX PROPORTION | REQUIRED STRENGTH | Comp sth in Kg/cm2 | Avg. Comp Kg/cm2 | LETTER No / DATED |
|-----------|-------------|--------------|--------------|--------------------|----------------|-------------------|--------------------|------------------|--|
| 1.1 | 6098 | | | | | | 195.56 | | No. WRD/SD I/WD II/ F.Estt/40/2021-22. DATED: 16-04-2021. |
| | 6099 | 3/4/2021 | 1/5/2021 | Foundation | 1.2.4 | 150 kg/cm2 | 186.67 | 186.67 | |
| | 6100 | | | | | | 177.78 | | |
| 1.2 | 6101 | | | | | | 186.67 | | do |
| | 6102 | 3/4/2021 | 1/5/2021 | Foundation | 1.2.4 | 150 kg/cm2 | 191.11 | 183.70 | |
| | 6103 | | | | | | 173.33 | | |
| 2.1 | 6104 | | | | | | 173.33 | | do |
| | 6105 | 5/4/2021 | 3/5/2021 | Foundation | 1.2.4 | 150 kg/cm2 | 173.33 | 170.37 | |
| | 6106 | | | | | | 164.44 | | |
| 2.2 | 6107 | | | | | | 177.78 | | do |
| | 6108 | 5/4/2021 | 3/5/2021 | Foundation | 1.2.4 | 150 kg/cm2 | 173.33 | 173.33 | |
| | 6109 | | | | | | 168.89 | | |
| 3.1 | 6110 | | | | | | 186.67 | | do |
| | 6111 | 7/4/2021 | 5/5/2021 | Wall | 1.2.4 | 150 kg/cm2 | 191.11 | 191.11 | |
| | 6112 | | | | | | 195.56 | | |
| 3.2 | 6113 | | | | | | 186.67 | | do |
| | 6114 | 7/4/2021 | 5/5/2021 | Wall | 1.2.4 | 150 kg/cm2 | 186.67 | 188.15 | |
| | 6115 | | | | | | 191.11 | | |
| 4.1 | 6116 | | | | | | 155.56 | | do |
| | 6117 | 9/4/2021 | 7/5/2021 | Wall | 1.2.4 | 150 kg/cm2 | 164.44 | 162.96 | |
| | 6118 | | | | | | 168.89 | | |
| 4.2 | 6119 | | | | | | 160.00 | | do |
| | 6120 | 9/4/2021 | 7/5/2021 | Wall | 1.2.4 | 150 kg/cm2 | 168.89 | 165.93 | |
| | 6121 | | | | | | 168.89 | | |

JUNIOR ENGINEER.

ASSISTANT ENGINEER

GOVERNMENT OF GOA
SD III (QC) , WRD, GOGAL, MARGAO- GOA.

NAME OF THE WORK: Protective wall for nallah in Sy.No. 318, 322 and for Pond in Sy.No. 63 in Village Velim in Velim Constituency.

SAMPLE SENT BY: AE, SD I, WD II, WRD, Rawanfond- Goa.

NAME OF THE AGENCY

TESTING PERIOD

28 days.

| REPORT NO | SAMPLE NOS. | CASTING DATE | TESTING DATE | LOCATION OF SAMPLE | MIX PROPORTION | REQUIRED STRENGTH | Comp sth in Kg/cm ² | Avg. Comp Kg/cm ² | LETTER No / DATED |
|-----------|-------------|--------------|--------------|--------------------|----------------|------------------------|--------------------------------|------------------------------|--|
| 5.1 | 6122 | | | | | | 177.78 | | No. WRD/SD I/WD II/ F.Estt/40/2021-22. DATED: 16-04-2021. |
| | 6123 | 12/4/2021 | 10/5/2021 | Wall | 1.2.4 | 150 kg/cm ² | 168.89 | 171.85 | |
| | 6124 | | | | | | 168.89 | | |
| 5.2 | 6125 | | | | | | 173.33 | | do |
| | 6126 | 12/4/2021 | 10/5/2021 | Wall | 1.2.4 | 150 kg/cm ² | 177.78 | 173.33 | |
| | 6127 | | | | | | 168.89 | | |
| 6 | 5882 | | | | | | 182.22 | | No. WRD/SD I/WD II/ F.Estt/43/2021-22. DATED: 19-04-2021. |
| | 5883 | 15-04-2021 | 13-05-2021 | Foundation | 1.2.4 | 150 kg/cm ² | 186.67 | 183.70 | |
| | 5884 | | | | | | 182.22 | | |
| 7 | 5885 | | | | | | 168.89 | | do |
| | 5886 | 16-04-2021 | 14-05-2021 | Foundation | 1.2.4 | 150 kg/cm ² | 182.22 | 179.26 | |
| | 5887 | | | | | | 186.67 | | |
| 8 | 5888 | | | | | | 182.22 | | do |
| | 5889 | 17-04-2021 | 15-05-2021 | Wall | 1.2.4 | 150 kg/cm ² | 173.33 | 176.29 | |
| | 5890 | | | | | | 173.33 | | |

JUNIOR ENGINEER.

ASSISTANT ENGINEER