

**GOVERNMENT OF GOA  
SD III (QC) , WRD, GOGAL, MARGAO- GOA.**

**NAME OF THE WORK:** Improvement and covering of nallah with RCC slab at various location in and around Khareband and Shirvodem in Margao Constituency.

**SAMPLE SENT BY:** AE, SD III, WD III, WRD, Gogol- Margao - Goa.

| NAME OF THE AGENCY |             |              |              | TESTING PERIOD                      |               | 07 days.          |                    |                  |  |
|--------------------|-------------|--------------|--------------|-------------------------------------|---------------|-------------------|--------------------|------------------|--|
| REPORT NO          | SAMPLE NOS. | CASTING DATE | TESTING DATE | LOCATION OF SAMPLE                  | MIX PROPOTION | REQUIRED STRENGTH | Comp sth in Kg/cm2 | Avg. Comp Kg/cm2 | LETTER No / DATED  |
| 1.1                | 7242        |              |              |                                     |               |                   | 106.67             |                  | No. 265/T/SD III/ WD<br>III/WRD/2021-22/58<br><b>DATED: 17-05-2021</b> |
|                    | 7243        | 10/5/2021    | 17-05-2021   | Walls @ Krishna Mandir Colconda     | 1.2.4         | 100 kg/cm2        | 120.00             | 114.08           |  |
|                    | 7244        |              |              | RHS Ch. (0-80) m                    |               |                   | 115.56             |                  |  |
| 1.2                | 7245        |              |              |                                     |               |                   | 115.56             |                  | do   |
|                    | 7246        | 10/5/2021    | 17-05-2021   | Walls @ Krishna Mandir Colconda     | 1.2.4         | 100 kg/cm2        | 115.56             | 114.08           |  |
|                    | 7247        |              |              | RHS Ch. (0-80) m                    |               |                   | 111.11             |                  |  |
| 2.1                | 7248        |              |              |                                     |               |                   | 173.33             |                  | do   |
|                    | 7249        | 11/5/2021    | 18-05-2021   | Walls @ Krishna Mandir Colconda     | 1.1.5.3       | 135 kg/cm2        | 168.89             | 171.85           |  |
|                    | 7250        |              |              | LHS Ch. (0-80) m                    |               |                   | 173.33             |                  |  |
| 2.2                | 7251        |              |              |                                     |               |                   | 173.33             |                  | do   |
|                    | 7252        | 11/5/2021    | 18-05-2021   | Walls @ Krishna Mandir Colconda     | 1.1.5.3       | 135 kg/cm2        | 168.89             | 170.37           |  |
|                    | 7253        |              |              | LHS Ch. (0-80) m                    |               |                   | 168.89             |                  |  |
| 3.1                | 7254        |              |              |                                     |               |                   | 164.44             |                  | do   |
|                    | 7255        | 12/5/2021    | 19-05-2021   | Walls @ Krishna Mandir Colconda     | 1.1.5.3       | 135 kg/cm2        | 168.89             | 167.41           |  |
|                    | 7256        |              |              | RHS Ch. (80-160) m                  |               |                   | 168.89             |                  |  |
| 3.2                | 7257        |              |              |                                     |               |                   | 173.33             |                  | do   |
|                    | 7258        | 12/5/2021    | 19-05-2021   | Walls @ Krishna Mandir Colconda     | 1.1.5.3       | 135 kg/cm2        | 168.89             | 170.37           |  |
|                    | 7259        |              |              | RHS Ch. (80-160) m                  |               |                   | 168.89             |                  |  |
| 4.1                | 7260        |              |              |                                     |               |                   | 111.11             |                  | do   |
|                    | 7261        | 13-05-2021   | 20-05-2021   | Walls @ Krishna Mandir Colconda RHS | 1.2.4         | 100 kg/cm2        | 106.67             | 109.63           |  |
|                    | 7262        |              |              | Ch. (160-210)m Bed Ch. (200-210)m   |               |                   | 111.11             |                  |  |
| 4.2                | 7263        |              |              |                                     |               |                   | 111.11             |                  | do   |
|                    | 7264        | 13-05-2021   | 20-05-2021   | Walls @ Krishna Mandir Colconda RHS | 1.2.4         | 100 kg/cm2        | 111.11             | 112.59           |  |
|                    | 7265        |              |              | Ch. (160-210)m Bed Ch. (200-210)m   |               |                   | 115.56             |                  |  |

**JUNIOR ENGINEER.**

**ASSISTANT ENGINEER**

**GOVERNMENT OF GOA**  
**SD III (QC) , WRD, GOGAL, MARGAO- GOA.**

**NAME OF THE WORK:** Improvement and covering of nallah with RCC slab at various location in and around Khareband and Shirvodem in Margao Constituency.

**SAMPLE SENT BY:** AE, SD III, WD III, WRD, Gogol- Margao - Goa.

| NAME OF THE AGENCY |             |              |              | TESTING PERIOD                     |               |                   | 07 days.           |                  |  |
|--------------------|-------------|--------------|--------------|------------------------------------|---------------|-------------------|--------------------|------------------|--|
| REPORT NO          | SAMPLE NOS. | CASTING DATE | TESTING DATE | LOCATION OF SAMPLE                 | MIX PROPOTION | REQUIRED STRENGTH | Comp sth in Kg/cm2 | Avg. Comp Kg/cm2 | LETTER No / DATED  |
| 5.1                | 7266        |              |              |                                    |               |                   | 120.00             |                  | No. 265/T/SD III/ WD<br>III/WRD/2021-22/58<br><b>DATED: 17-05-2021</b> |
|                    | 7267        | 14-05-2021   | 21-05-2021   | Walls @ Krishna Mandir Colconda    | 1.2.4         | 100 kg/cm2        | 124.44             | 121.48           |  |
|                    | 7268        |              |              | LHS Ch. (80-160) m                 |               |                   | 120.00             |                  |  |
| 5.2                | 7269        |              |              |                                    |               |                   | 120.00             |                  | do   |
|                    | 7270        | 14-05-2021   | 21-05-2021   | Walls @ Krishna Mandir Colconda    | 1.2.4         | 100 kg/cm2        | 115.56             | 117.04           |  |
|                    | 7271        |              |              | LHS Ch. (80-160) m                 |               |                   | 115.56             |                  |  |
| 6.1                | 7272        |              |              |                                    |               |                   | 115.56             |                  | do   |
|                    | 7273        | 15-05-2021   | 22-05-2021   | Walls @ Krishna Mandir Colconda    | 1.2.4         | 100 kg/cm2        | 124.44             | 120.00           |  |
|                    | 7274        |              |              | LHS Ch. (160-210) m                |               |                   | 120.00             |                  |  |
| 6.2                | 7275        |              |              |                                    |               |                   | 120.00             |                  | do   |
|                    | 7276        | 15-05-2021   | 22-05-2021   | Walls @ Krishna Mandir Colconda    | 1.2.4         | 100 kg/cm2        | 120.00             | 118.52           |  |
|                    | 7277        |              |              | LHS Ch. (160-210) m                |               |                   | 115.56             |                  |  |
| 7                  | 7671        |              |              |                                    |               |                   | 142.22             |                  | No. 265/T/SD III/ WD<br>III/WRD/2021-22/<br><b>DATED: 25-05-2021</b>   |
|                    | 7672        | 18-05-2021   | 25-05-2021   | Slab at Krishna Mandir,            | 1.1.5.3       | 135 kg/cm2        | 151.11             | 148.15           |  |
|                    | 7673        |              |              | Ch. (0-108.63)m                    |               |                   | 151.11             |                  |  |
| 8                  | 7674        |              |              |                                    |               |                   | 151.11             |                  | do   |
|                    | 7675        | 19-05-2021   | 26-05-2021   | Slab at Krishna Mandir,            | 1.1.5.3       | 135 kg/cm2        | 142.22             | 145.18           |  |
|                    | 7676        |              |              | Ch. (108.63- 190.81)m              |               |                   | 142.22             |                  |  |
| 9                  | 7677        |              |              |                                    |               |                   | 115.56             |                  | do   |
|                    | 7678        | 20-05-2021   | 27-05-2021   | Walls @ Krishna Mandir bed & walls | 1.2.4         | 100 kg/cm2        | 124.44             | 120.00           |  |
|                    | 7679        |              |              |                                    |               |                   | 120.00             |                  |  |
| 10                 | 7680        |              |              |                                    |               |                   | 142.22             |                  | do   |
|                    | 7681        | 21-05-2021   | 28-05-2021   | Slab at Krishna Mandir,            | 1.1.5.3       | 135 kg/cm2        | 151.11             | 148.15           |  |
|                    | 7682        |              |              | Ch. (190.81-210)m + junctions      |               |                   | 151.11             |                  |  |

**JUNIOR ENGINEER.**

**ASSISTANT ENGINEER**

**GOVERNMENT OF GOA**  
**SD III (QC) , WRD, GOGAL, MARGAO- GOA.**

**NAME OF THE WORK:** Improvement and covering of nallah with RCC slab at various location in and around Khareband and Shirvodem in Margao Constituency.

**SAMPLE SENT BY:** AE, SD III, WD III, WRD, Gogol- Margao - Goa.

| NAME OF THE AGENCY |             |              |              | TESTING PERIOD                       |               | 07 days.          |                    |                  |  |
|--------------------|-------------|--------------|--------------|--------------------------------------|---------------|-------------------|--------------------|------------------|--|
| REPORT NO          | SAMPLE NOS. | CASTING DATE | TESTING DATE | LOCATION OF SAMPLE                   | MIX PROPOTION | REQUIRED STRENGTH | Comp sth in Kg/cm2 | Avg. Comp Kg/cm2 | LETTER No / DATED  |
| 11.1               | 7683        |              |              |                                      |               |                   | 120.00             |                  | No. 265/T/SD III/ WD<br>III/WRD/2021-22/<br><b>DATED: 25-05-2021</b>   |
|                    | 7684        | 22-05-2021   | 29-05-2021   | Walls Foundation @ Kudchadkar        | 1.2.4         | 100 kg/cm2        | 120.00             | 118.52           |  |
|                    | 7685        |              |              | Hospital                             |               |                   | 115.56             |                  |  |
| 11.2               | 7686        |              |              |                                      |               |                   | 115.56             |                  | do   |
|                    | 7687        | 22-05-2021   | 29-05-2021   | Walls Foundation @ Kudchadkar        | 1.2.4         | 100 kg/cm2        | 115.56             | 118.52           |  |
|                    | 7688        |              |              | Hospital                             |               |                   | 124.44             |                  |  |
| 12                 | 7689        |              |              |                                      |               |                   | 120.00             |                  | do   |
|                    | 7690        | 24-05-2021   | 31-05-2021   | 1st Lift walls @ Kudchadkar Hospital | 1.2.4         | 100 kg/cm2        | 120.00             | 120.00           |  |
|                    | 7691        |              |              |                                      |               |                   | 120.00             |                  |  |
| 13                 | 7745        |              |              |                                      |               |                   | 173.33             |                  | No. 265/T/SD III/ WD<br>III/WRD/2021-22/93<br><b>DATED: 14-06-2021</b> |
|                    | 7746        | 7/6/2021     | 14-06-2021   | Near Nitin Prabhudesai, Slab         | 1.1.5.3       | 135 kg/cm2        | 168.89             | 170.37           |  |
|                    | 7747        |              |              |                                      |               |                   | 168.89             |                  |  |
| 14.1               | 7748        |              |              |                                      |               |                   | 164.44             |                  | do   |
|                    | 7749        | 8/6/2021     | 15-06-2021   | Walls near Antonio house             | 1.1.5.3       | 135 kg/cm2        | 168.89             | 167.41           |  |
|                    | 7750        |              |              |                                      |               |                   | 168.89             |                  |  |
| 14.2               | 7751        |              |              |                                      |               |                   | 173.33             |                  | do   |
|                    | 7752        | 8/6/2021     | 15-06-2021   | Walls near Antonio house             | 1.1.5.3       | 135 kg/cm2        | 168.89             | 170.37           |  |
|                    | 7753        |              |              |                                      |               |                   | 168.89             |                  |  |
| 15.1               | 7754        |              |              |                                      |               |                   | 115.56             |                  | do   |
|                    | 7755        | 9/6/2021     | 16-06-2021   | Wall foundation of 2m wall @         | 1.2.4         | 100 kg/cm2        | 115.56             | 118.52           |  |
|                    | 7756        |              |              | Kudchadkar Hospital                  |               |                   | 124.44             |                  |  |
| 15.2               | 7757        |              |              |                                      |               |                   | 120.00             |                  | do   |
|                    | 7758        | 9/6/2021     | 16-06-2021   | Wall foundation of 2m wall @         | 1.2.4         | 100 kg/cm2        | 120.00             | 120.00           |  |
|                    | 7759        |              |              | Kudchadkar Hospital                  |               |                   | 120.00             |                  |  |

**JUNIOR ENGINEER.**

**ASSISTANT ENGINEER**

**GOVERNMENT OF GOA**  
**SD III (QC) , WRD, GOGAL, MARGAO- GOA.**

**NAME OF THE WORK:** Improvement and covering of nallah with RCC slab at various location in and around Khareband and Shirvodem in Margao Constituency.

**SAMPLE SENT BY:** AE, SD III, WD III, WRD, Gogol- Margao - Goa.

| NAME OF THE AGENCY |             |              |              | TESTING PERIOD                         |               | 07 days.          |                    |                  |  |
|--------------------|-------------|--------------|--------------|--|---------------|-------------------|--------------------|------------------|--|
| REPORT NO          | SAMPLE NOS. | CASTING DATE | TESTING DATE | LOCATION OF SAMPLE                     | MIX PROPOTION | REQUIRED STRENGTH | Comp sth in Kg/cm2 | Avg. Comp Kg/cm2 | LETTER No / DATED  |
| 16.1               | 7760        |              |              | 2nd Lift @ Kudchadkar Hospital +       |               |                   | 106.67             |                  | No. 265/T/SD III/ WD<br>III/WRD/2021-22/93<br><b>DATED: 14-06-2021</b> |
|                    | 7761        | 10/6/2021    | 17-06-2021   | Wall foundation of 2m wall @           | 1.2.4         | 100 kg/cm2        | 120.00             | 114.08           |  |
|                    | 7762        |              |              | Kudchadkar Hospital                    |               |                   | 115.56             |                  |  |
| 16.2               | 7763        |              |              | 2nd Lift @ Kudchadkar Hospital +       |               |                   | 115.56             |                  | do   |
|                    | 7764        | 10/6/2021    | 17-06-2021   | Wall foundation of 2m wall @           | 1.2.4         | 100 kg/cm2        | 115.56             | 114.08           |  |
|                    | 7765        |              |              | Kudchadkar Hospital                    |               |                   | 111.11             |                  |  |
| 17.1               | 7766        |              |              |  |               |                   | 111.11             |                  | do   |
|                    | 7767        | 11/6/2021    | 18-06-2021   | Wall Foundation of 1.2m wall &3rd Lift | 1.2.4         | 100 kg/cm2        | 106.67             | 109.63           |  |
|                    | 7768        |              |              | of 2.5m wall @ Kudchadkar Hospital     |               |                   | 111.11             |                  |  |
| 17.2               | 7769        |              |              |  |               |                   | 111.11             |                  | do   |
|                    | 7770        | 11/6/2021    | 18-06-2021   | Wall Foundation of 1.2m wall &3rd Lift | 1.2.4         | 100 kg/cm2        | 111.11             | 112.59           |  |
|                    | 7771        |              |              | of 2.5m wall @ Kudchadkar Hospital     |               |                   | 115.56             |                  |  |
| 18.1               | 7772        |              |              |  |               |                   | 120.00             |                  | do   |
|                    | 7773        | 12/6/2021    | 19-06-2021   | Wall of 1.2 m ht, 1st Lift of 2m ht    | 1.2.4         | 100 kg/cm2        | 120.00             | 118.52           |  |
|                    | 7774        |              |              | Wall @ Kudchadkar Hospital             |               |                   | 115.56             |                  |  |
| 18.2               | 7775        |              |              |  |               |                   | 115.56             |                  | do   |
|                    | 7776        | 12/6/2021    | 19-06-2021   | Wall of 1.2 m ht, 1st Lift of 2m ht    | 1.2.4         | 100 kg/cm2        | 115.56             | 118.52           |  |
|                    | 7777        |              |              | Wall @ Kudchadkar Hospital             |               |                   | 124.44             |                  |  |
| 18.3               | 7778        |              |              |  |               |                   | 120.00             |                  | do   |
|                    | 7779        | 12/6/2021    | 19-06-2021   | Wall of 1.2 m ht, 1st Lift of 2m ht    | 1.2.4         | 100 kg/cm2        | 120.00             | 120.00           |  |
|                    | 7780        |              |              | Wall @ Kudchadkar Hospital             |               |                   | 120.00             |                  |  |
| 19.1               | 7781        |              |              |  |               |                   | 111.11             |                  | do   |
|                    | 7782        | 13-06-2021   | 20-06-2021   | 2nd Lift of 2 m ht wall @              | 1.2.4         | 100 kg/cm2        | 106.67             | 109.63           |  |
|                    | 7783        |              |              | Kudchadkar Hospital                    |               |                   | 111.11             |                  |  |

**JUNIOR ENGINEER.**

**ASSISTANT ENGINEER**

**GOVERNMENT OF GOA**  
**SD III (QC) , WRD, GOGAL, MARGAO- GOA.**

**NAME OF THE WORK:** Improvement and covering of nallah with RCC slab at various location in and around Khareband and Shirvodem in Margao Constituency.

**SAMPLE SENT BY:** AE, SD III, WD III, WRD, Gogol- Margao - Goa.

**NAME OF THE AGENCY**

**TESTING PERIOD**

07 days.

| REPORT NO | SAMPLE NOS. | CASTING DATE | TESTING DATE | LOCATION OF SAMPLE        | MIX<br>PROPOTION | REQUIRED<br>STRENGTH | Comp sth in<br>Kg/cm2 | Avg. Comp<br>Kg/cm2 | LETTER No / DATED        |
|-----------|-------------|--------------|--------------|---------------------------|------------------|----------------------|-----------------------|---------------------|--------------------------|
| 16.1      | 7784        |              |              |                           |                  |                      | 120.00                |                     | No. 265/T/SD III/ WD     |
|           | 7785        | 13-06-2021   | 20-06-2021   | 2nd Lift of 2 m ht wall @ | 1.2.4            | 100 kg/cm2           | 120.00                | 120.00              | III/WRD/2021-22/93       |
|           | 7786        |              |              | Kudchadkar Hospital       |                  |                      | 120.00                |                     | <b>DATED: 14-06-2021</b> |

**JUNIOR ENGINEER.**

**ASSISTANT ENGINEER**