## GOVERNMENT OF GOA OFFICE OF THE ASSISTANT ENGINEER SUB DIVISION III (SOUTH), QUALITY CONTROL LABORATORY, WATER RESOURCES DEPARTMENT, GOGAL, MARGAO- GOA.

## PLEASE FIND THE TEST RESULTS OF CEMENT AS DETAILED BELOW:

Name of work:- Improvement and development of bund in Sy.No. 33/1 Orlim in Benaulim Constituency.

Type of Cement: Ordinary Portland cement Brand / Grade: JSW /43 grade

Source of receipt: Assistant Engineer, SD I, WD II, WRD, Rawanfond- Goa.

Ref. Letter No: WRD/SD I/WD II/F. Estt /553/2022-23. Dated: 15-12-2022.

**Qty. Represented:** 

L.S. No: F.28/05/2022.

## **Physical Properties**

Sr.	Description	Test results	Requirements as per I.S.
No	-		
1	Fineness. (% retained on 9	3 %	Not more than 10%
	micron sieve)		
2	Setting Time in (Minutes)		
	lxxix) Initial	186 minutes	Not less than 30 Min
	lxxx) Final.	294 minutes	Not more than 600 Min.
3	Minimum Com Strength Kg/Cm <sup>2</sup>		
	i) 72 hrs. $\pm 1$ hrs.	393.33Kg/cm2	Not less than 230.0Kg/cm2
	ii) 168 hrs. ±2hrs	490.00Kg/cm2	Not less than 330.0Kg/cm2
	iii) 672 hrs. ±4 hrs	576.66 Kg/cm2	Not less than 430.0Kg/cm2
4	Consistency of cement.	28 %	

To,

The Asst. Engineer.SD I, WD II, WRD, Rawanfond- Goa. Copy Submitted to:

- 1. The Exe. Eng. W.D. XI, WRD, Rawanfond-Goa.
- 2. S.W.II, CPO, WRD, Sinchai Bhavan , Alto, Porvorim Goa.

3. Office file.

**Junior Engineer** 

**Assistant Engineer**