

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III. (C.P.O) QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / CPO / SDIII / F.59 / / 2019-20 dated: - 12 -2019.

Name of the Work: Construction of R.C.C box Conduit near Kenybab hotel in Fatorda Constituency Salcete-Goa

Sample Sent by: Assistant Engineer, SD III, WD III, WRD, Gogol, Margao, Goa.

Letter No: 233/SD III/WD III/WRD/19-20/282

Dated:- 12/11/2019

Received on: 25/11/2019

Date of Testing: 2/12/2019

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
4675/19	Coarse Sand	FM Silt & Clay Grading	2.871 2.50% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
4676/19	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate nominal size blend
4677/19	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	20mm & 10 mm metal in 1:1 proportion.

Dhananjay R Nagvenkar
Technical Assistant

Pravin C Parsekar
Assistant Engineer

- Copy submitted to
- 1) Assistant Engineer, SD III, WD III, WRD, Gogol, Margao, Goa.
 - 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
 - 3) Executive Engineer, WD III, WRD, Ponda, Goa.
 - 4) Office File.