GOVERNMENT OF GOA WATER RESOURCES DEPARTMENT S.D.III, WORK DIVISION XI, QUALITY CONTROL

GOGAL, MARGAO- GOA

NO: WRD / WD XI / SD	III/ F.59 / W.F. 83/2021/ 30 / 2021-22.	Dated: 07-05-2021		
Name of the Work :-	Construction of Retaining wall for the nalla	h in Sy. No. 242/1 at Senaulim in V.P. Verna	in Nuvem Constituency.	
REQUISITION DETAILS	: NO: WRD / SD I/ WD II/ F.Estt/91/ 2021-2	2. Dated:- 05-05-2021		
SAMPLE SENT BY: Assistant Engineer, Sub. Div. I, Works Div. II, WRD, Rawanfond- Goa.				
SAMPLE RECEIVED ON:	5/5/2021			
TYPE OF SAMPLE: Lat	trite boulders			
STRENGTH REQUIRED:				
TESTING DATE:	7/5/2021			
TESTED BY:	Junior Engineer	AUTHORISED BY:	AE, SD III, QC.	
AGENCY NAME:				
Sr. No:	SAMPLE NUMBER	Comp. strength in K _E	;/sq.cm. AVERAGE Kg/sq.cm	
1	438	37.50		
2	439	40.00	40.00	
3	440	41.67	41.67 39.33	
4	441	37.50	37.50	
5	442	40.00		

Junior Engineer

Assistant Engineer

Assistant Engineer, Sub- Div. I, Works Div. II, WRD, Rawanfond- Goa.

Copy Submitted To:

Τo,

- 1. Executive Engineer, Works Div. XI, WRD, Rawanfond-Goa.
- 2. Office File No: F-59